

UNCONFIRMED RUMOUR



I've been told that a foreign construction worker had fallen to his death, and given a video of his broken face and body which I declined to look.

I requested a photo of the workers on scaffolding without any harness.

Safety experts, is this ok?

P/S: According to the inhabitants next door to this project, the construction workers work until late in the night without sufficient lighting, some work without safety helmets and boots and certainly no harnesses.

Is this legal and how can we take the developers to book? More undocumented deaths will happen if we don't speak up.

Taken at Residensi PandanMas 2 project by #AsetKayamas and #DBKL

Animah Kosai, Nancy S Y Sim Lim



20 likes • 27 comments

PERSONAL PROTECTIVE EQUIPMENT



RUMOUR CLARIFICATION

With regard to a rumour circulating on social media about the death of a contractor's worker resulting from a fall, Aset Kayamas would like to clarify and inform the general public that the rumour is completely untrue. The contractor's workers are healthy and they are still working at the construction site. We are always committed to ensuring the contractors operate according to safety requirements as well as supervising all our work in compliance with rules and regulations applicable to construction work. In this respect, every construction worker is required to comply with the safety guidelines and instructions to carry out the work at site. The contractors are required to ensure that suitable personal protective equipment (e.g. safety helmet) is provided and is properly worn by the workers. Contractors who fail to comply with the regulations may be imposed serious penalties or their contract may be terminated. Please accept our sincere apologies for the bad feeling you may have experienced in response to this rumour.

Thank you!



www.asetkayamas.com

